## azard Alert ive omorrow



## **SAFETY KEYPOINTS:**

Roof and rib conditions constantly change in mines

when he was struck by a large piece of unbolted top.

All miners share responsibility to monitor work areas for hazards

If a rib or piece of roof must be pulled, always use a proper bar of suitable length and ensure there is a safe amount of clearance

Miners must never place themselves under unsupported top

